





Grinding Wheel Common Shape Chart 1


1A1




3A1




14A1




6A1




1A1 - Centerless Large Wheel



1A1R - Tool




9A1




1A1R



1Y1




1DD1






Grinding Wheel Common Shape Chart 2


1E1




1EE1




1F1




1FF1




1FF1 R-Tool




1V1




2A2T




4A2P



6A2




6A2B






Grinding Wheel Common Shape Chart 3


6A2C




6A2H




6A9




9A3




11A2



11V9



12A2



12V9

